
C408 & R391 are 0603 size parts
R391 will be placed between one pad of C408 and the
Base pad of Q37
gain problem
changed from J310 to 2SK1470
test only
2nd pll lock detect
not used in production
Use a no fill around line
mount reg to chassis
Analog supply 1.8V
Digital supply
Digital DVDD 3.3v
ANALOG 3.3 3.3v
-8V supply
I/O Update
DATA
CLK
/CS
DATA_U2
CLK_U2
LE_U2
11-12-04
Ten-Tec Inc.
1185 Dolly Parton Parkway
Sevierville, Tn 37862
588SYN_mmic_REV
October 12, 2006